




0.15% C₃H₆, 0.68% O₂ in N₂, $\Phi = 1.00$, $p = 1.0$ atm, $T = 1200$ K




0.15% C₃H₆, 0.68% O₂ in N₂, $\Phi = 1.00$, $p = 1.0$ atm, $T = 1200$ K




0.15% C₃H₆, 0.68% O₂ in N₂, $\Phi = 1.00$, $p = 1.0$ atm, $T = 1200$ K




0.15% C₃H₆, 0.68% O₂ in N₂, $\Phi = 1.00$, $p = 1.0$ atm, $T = 1200$ K




0.15% C₃H₆, 0.68% O₂ in N₂, $\Phi = 1.00$, $p = 1.0$ atm, $T = 1200$ K




0.15% C₃H₆, 0.68% O₂ in N₂, $\Phi = 1.00$, $p = 1.0$ atm, $T = 1200$ K




0.15% C₃H₆, 0.68% O₂ in N₂, $\Phi = 1.00$, $p = 1.0$ atm, $T = 1200$ K




0.15% C₃H₆, 1.35% O₂ in N₂, $\Phi = 0.50$, $p = 5.0$ atm, $T = 1050$ K




0.15% C₃H₆, 1.35% O₂ in N₂, $\Phi = 0.50$, $p = 5.0$ atm, $T = 1050$ K




0.15% C₃H₆, 1.35% O₂ in N₂, $\Phi = 0.50$, $p = 5.0$ atm, $T = 1050$ K




0.15% C₃H₆, 1.35% O₂ in N₂, $\Phi = 0.50$, $p = 5.0$ atm, $T = 1050$ K




0.15% C₃H₆, 1.35% O₂ in N₂, $\Phi = 0.50$, $p = 5.0$ atm, $T = 1050$ K



0.15% C₃H₆, 1.35% O₂ in N₂, $\Phi = 0.50$, $p = 5.0$ atm, $T = 1050$ K



0.15% C₃H₆, 1.35% O₂ in N₂, $\Phi = 0.50$, $p = 5.0$ atm, $T = 1050$ K



0.15% C₃H₆, 1.35% O₂ in N₂, $\Phi = 0.50$, $p = 5.0$ atm, $T = 1050$ K

